

Audit Details

Audit name:	ERT - Simulacro / ERT - Drill
Audit date:	10/09/2023
Auditor:	David Pinto
Audit details:	Simulacro en áreas de trabajo / Work Area Drill
Overall Outcome:	Completed
Emergencia / Emergency	Emergencias medicas o por lesion / Medical or injury emergencies
Breve descripción del evento / Brief Event Description	09 de septiembre 2023, Simulacro PP Ops Screening Plant colaborador Cae en la chuta. September 09, 2023, Simulation PP Ops Screening Plant collaborator Falls in the chute.
Especificar ubicación / Specify Location	Screening Plant 312-CH-1626
Hora de inicio / Starting Time	16:07
Hora de finalización / Ending Time	17:30
Departamento / Department	PP OPS - Primary Crushing

Notes

09 de septiembre 2023, Simulacro PP Ops Screening Plant colaborador Cae en la chuta.

COMENTARIOS ADICIONALES

- Sugerimos al equipo de rescate aprovechar las detenciones por mantenimiento para que desarrolle o actualice un protocolo de extracción en las diferentes áreas de la planta.
- Repasar el protocolo del plan de emergencia durante las pláticas de seguridad.
- Sensibilizar al personal de la Planta sobre la importancia de la comunicación con el equipo en las situaciones de emergencia.
- Coordinar con el personal de otros departamentos; mecánicos, instrumentistas, electricistas, etc. simulacros de rescate dentro de la planta.
- Colocar a ambos lados las señales de punto de encuentro en puntos donde sea necesario.
- En el simulacro no tuvimos la presencia del personal de seguridad ocupacional.
- No se dio la llegada del personal de protección física al lugar del simulacro.
- En la charla de seguridad de inicio de turno los compañeros preguntaron ¿Porqué a la víctima no se le colocó el cuello ortopédico antes de sacarlo del chute

September 09, 2023, Simulation PP Ops Screening Plant collaborator Falls in the chute.

ADDITIONAL COMMENTS

- We suggest that the rescue team take advantage of maintenance shutdowns to develop or update an extraction protocol in the different areas of the plant.
- Review the emergency plan protocol during safety talks.
- Sensitize plant personnel on the importance of communication with the team in emergency situations.
- Coordinate with personnel from other departments; mechanics, instrumentalists, electricians, etc. rescue drills within the plant.
- Place meeting point signs on both sides at points where necessary.
- In the drill we did not have the presence of occupational safety personnel.
- Physical protection personnel did not arrive at the drill site.
- During the safety talk at the beginning of the shift, the colleagues asked why the victim was not fitted with the orthopedic collar before being taken out of the chute.

Response Summary

Section	Completed	Not completed
Audit	1	0

Audit Criteria

#	Criteria	Details	Response
1	Completed Drill	Responsible will determine the drill	Completed

Signatures

Capacity: supervisor

Name: David Pinto



Documents




debreafig.jpg



evacuacion de paciente por escaleras.jpg



extraccion de la chuta.jpg



sistema de ventaja mecanica con Brigadistas del area.jpg



acceso a paciente.jpg

DOC - Evaluacion de simulacro screening Plant 09092023.doc